

Research Operations Division

Boundary Physics (*H. Kugel*)

- ◆ Vessel interior in good condition - no cracked tiles
 - ▶ White dust/fibers on horizontal surfaces at 3 – 4 cm⁻²
 - ▶ At lower CHI gap some discoloration on BN shields
 - ▶ At upper CHI gap, darkened areas on skirt of insulator
 - originated at gap between BN tiles covering shelf
 - tiles also covered with graphite chips
- ◆ Lithium Pellet Injector
 - ▶ Evaluated propellant valve
 - ▶ Fabricating pneumatic and computer controls
- ◆ Supersonic Gas Injector (Mach 8)
 - ▶ Delivery of graphite nozzles expected in about 3 weeks
 - ▶ Took Schlieren photographs of shock from Mach 2 nozzle on loan from M&AE department
- ◆ Wall coupons from FY03 run sent to Sandia for accelerator-based analysis
 - ▶ already analyzed using AES, XPS, SIMS
- ◆ New data and status of NSTX edge transport modeling effort placed in the NSTX UEDGE directories

Research Operations Division

Diagnostics (*D. Johnson, R. Kaita*)

- ◆ Taking advantage of time before the TF construction “crunch” to complete several diagnostic tasks
 - ▶ Spatial calibrations of
 - Edge rotation diagnostic
 - Neutral particle analyzer
 - Fast reciprocating probe
 - Toroidal CHERS (+ “white-plate” calibration)
 - VB sightlines
 - ▶ Checked connections for high frequency Mirnov coils
 - ▶ Investigated failure of 3 B_p sensors
 - Making better shields
 - ▶ Replace damaged detectors in USXR arrays
 - ▶ Repaired flux loops behind secondary passive plates
 - ▶ Move internal heating/cooling pipes obstructing diagnostic access
- ◆ Calibration work was interrupted by failure of the Faro measuring arm
 - ▶ Not expected back from repair until next week

Research Operations Division

Diagnostics [2]

- ◆ Tangential bolometer array performance degraded during the last run
 - ▶ Found coating deposited on sensor array which manufacturer etched away
 - ▶ Was detector exposed to GDC or boronization?
 - Archive shutter status for *post mortem* analysis
- ◆ Successful CDR for high-k tangential microwave scattering diagnostic
 - ▶ Launch 1mm microwave beam through NB armor at Bay H and collect scattered radiation along an array of sightlines through Bay K
- ◆ Developing proposal to slot upper and lower outer divertor plates to permit views of NB for poloidal rotation measurement

Research Operations Division

RF Systems (*R. Wilson*)

- ◆ No sign of arcing in the antenna feedthroughs since modifications
- ◆ Developing system to use feedback on plasma radial position to control antenna loading
 - ▶ Modified the RF monitoring circuits in NTC to improve frequency response
 - ▶ Blocked out method for data acquisition to real-time control computer
- ◆ Completed the remote timer for RF sources
 - ▶ Can now set up RF pulse from NSTX Control Room
- ◆ Repaired the dummy load coolant tank
- ◆ Starting design of symmetrical end-feed for antennas
- ◆ Much effort is being shifted to C-Mod, DIII-D and ITER

Research Operations Division

Physics Operations (*D. Mueller*)

- ◆ Model plasma response for extending RT-EFIT control (with GA collaborators)
 - Improve vertical stability and increase κ .
 - Optimize gains and include non-diagonal terms for shape control
- ▶ Power supply model developed (Hatcher)
- ▶ Updated information about NSTX structural elements (Menard)
- ▶ Measure feedback system delays (Marsala, Gibney)
- ◆ Continue collaboration with HIT group (UW) on adding CHI to inductive discharge (Mueller)
 - ▶ Scheduled experiments this July/August
- ◆ GIS upgrade
 - ▶ Separate control system for CS and shoulder gas puffers