



U.S. DEPARTMENT OF
ENERGY


Office of
Science



Shutdown Handler and Non-Inductive Current Calculations

S. P. Gerhardt, D. Battaglia, R. Bell, M.D. Boyer,
A. Diallo, K. Erickson, S. Kaye, B.P. LeBlanc,
D. Mueller, C. Myers, M. Podesta, S. Sabbagh

2016 NSTX-U Results Review, ASC Session
LSB B318
9/21/16



Shutdown Handler Designed to Gracefully End the Plasma

- State machine implementation
- Coding of the state machine is largely free of detailed plasma physics/control.
- Why do this?
 - Want to limit control transients at the end of the discharge.
 - Want to support critical research in disruption detection/avoidance.




Diagram of the State Machine Presently Implemented in PCS

What Controls, and is Controlled By, the Shutdown Handler?

Controls It

- Can go into fast rampdown by:
 - Detection of large $n=1$ mode.
 - Detection of large loss of plasma current.
 - Detection of excessive vertical motion.
 - I_p drops beneath value required for rtEFIT while using ISOFLUX
 - Operator request
- Can go into slow rampdown by:
 - Detection that OH coil is approaching a heating limit.
 - Detection that OH coil is approaching a current limit.
 - Operator request


It Controls

- At each state change, can change the control algorithm used by the shape & position, TF, OH, gas, NBI, LGI, ModeID & RWM control codes.

Shutdown Handler Used to Create Smooth L-Mode Rampdown



- Three AM fiducial shots from week of 4/4/2016.
- Single operator waveform modified at $t=1.5$ to start the rampdown.
- Rampdown is IWL, with power and I_p slowly ramped off.

L-mode Rampdowns Triggered By a Single Switch



Shutdown Handler Also Used to End Failing Discharges

- Shot requested to go longer, but vertical motion detected.
- Rampdown initiated.
- Plasma inboard limited, only slowly drifts up.




Slow Drift Up, But No VDE or Disruption

Next Steps





- During this run, we never activated the part of code allowing a transition from slow to fast rampdown:
 - Noticed on May 16th that reason was the settings in the system category during the slow rampdown phase.
 - Tried it on May 20th, but had a code bug.
 - Fixed the bug, but didn't get a chance to test it.
- Need to allow the RWM sensors to trigger the rampdown
 - Clayton Myers had them running great, never flipped the switches.
- Need to see if some other configuration of the vertical position sensing code can be less sensitive to $n=1$ modes.

Non-Inductive Current Fraction Overview

- Operations with high non-inductive fraction (f_{NI}) is a prominent goal of NSTX-U.
- This quantity, and its sub-components, are typically computed with TRANSP.
- Don't have good T_i data for the shots under consideration, so simply using BEAST runs.
 - Recognize that these are approximations/estimates



Best Shot has (Transiently) $f_{NI} \sim 60\%$, More Sustained Shots Have $f_{NI} \sim 40\%$




Next Steps

- Not a lot of new analysis jumping out at me.
- Primarily, continue the scenario development tasks:
 - Early H-mode
 - Higher elongation
 - Error field correction
 - RWM control for higher β_N
- Get more routine T_i data
 - Use the modulation tricks that Ron has recommended

Backup

Database Analysis Shows the Most Common Path Through States

- Most likely the go from **Flat-Top** through **Fast Shutdown** to **Insufficient I_p** .
 - These are all the failing plasmas.
- Somewhat likely the go from **Flat-Top** through **Slow Shutdown** to **Insufficient I_p** .
 - These were the L-mode rampdowns.
- Last common case was **Flat-Top** directly to **Insufficient I_p** .
 - These are shots that failed to ramp-up...fizzles.



*Need to revisit
the OH LoC
Cases. Are
these real?*

Database Analysis Shows the Causes of Leaving Flat-Top

- By far the most common is **Vertical Position Loss of Control (LoC)**
 - But beware, those sensors are sensitive to $n=1$ modes as well as $n=0$,
- **OH Near LoC** triggers shutdown based on OH current or heating limit.
- **I_p LoC** looks for large values of the I_p error.
- We never activated the **BP & BR $n=1$ LoC**.
 - Therefore don't read anything into its having no instances...wait till next year.

