



NSTX TF JOINT RE-DESIGN

C. Neumeyer

and the NSTX Team



20th IEEE/NPSS Symposium on Fusion Engineering




October 14-17, 2003

Topics

- TF Coil Description
- Failure of Original Assembly
- Forces, Thermal Effects, Load Paths
- Contact Resistance Considerations
- Features of New Design
- Status of Recovery Effort


TF COIL DESCRIPTION

- 36 Turn Copper Coil, Water Cooled
- $B_t \leq 6\text{kG}$ at $R_0=0.854\text{m}$
- $I_{\text{tf}} \leq 71.2\text{kA/turn}$



Note: Original design shown

ORIGINAL TF JOINT ELEMENTS




Note: Original Design Shown


FLAGS, SHIMS, WEDGES

Original Split Flag

Original Wedges and Shims




Split flag to facilitate joint resistance measurement




Inadequate Communication of Loads from Flags to Hub

Note: Original Design Shown

February 14, 2003: Following our morning “test shots”, the first plasma attempt of the day resulted in a loud bang (heard on the control room audio monitors) accompanied by a plume of smoke (visible on the control room video monitors).



Initial inspection revealed that one of the TF “flags” on the bottom end of the machine was displaced radially by about 1 inch



Subsequent inspection revealed the extent of the damage


Peak Damage Region




Mating Flaps



PEAK DAMAGE AREA




FAULT SCENARIO




- An open circuit fault at flag joint
- Short circuit fault across coil terminals
- Spike of fault current from the power supply through short circuit
- Power supply tripped, current spike decay
- L/R decay of the coil current
- The energy dissipated in the arc was of order 1.4MJ.

FAILURE OF JOINT



FAILURE OF JOINT



Lack of Hub Stiffness and Shortcomings of Shimming Scheme Led to Cyclic Overload of Fasteners and Eventual Failure

FUNCTIONS OF JOINT

Mechanical Function

Preload for High Contact Pressure

Structural Support Against EM & Thermal Loads


Maintain High Contact Pressure

Low Electrical Resistance and Dissipation

Peak Temperature within Limit

Electrical Function

CURRENT WAVEFORMS




- Design basis $\int I^2 T = 6.5 \times 10^9 \text{ A}^2\text{-s}$ which causes adiabatic ΔT of 80°C in Cu

- 6kG pulse is most critical for joint since forces are maximum and time for heat diffusion is minimum

- NSTX Research Plan requires only 5% of pulses at 6kG, remainder primarily at 3 and 4.5kG

EM FORCES




- In-Plane ■
 - vertical load and moment due to magnetic pressure from self-field

- Out-of-Plane ■
 - lateral due to $I_{tf} \times B_{z(oh\&pf)}$
 - torsional due to $I_{tf} \times B_{r(oh\&pf)}$

Notes:

- 1) All coils assumed at full current, worst case polarity (conservative)
- 2) Forces equal and opposite on two ends of bundle


LOAD PATHS



THERMAL EFFECTS

- Vertical length of inner leg bundle from bottom to top increases by up to 0.35" (~ 9mm) during a pulse
- Radius of inner leg bundle increases bundle increases by approximately 0.006" (0.15mm) during a pulse
- Flag heats modestly during pulse ($\Delta T \approx 5^\circ\text{C}$) but can ratchet to $\Delta T \leq 25^\circ\text{C}$ at rated duty cycle (conservative), $\Delta r \approx 0.005$ " (0.1mm) in length

CONTACT RESISTANCE




Tolerable Resistivity
 $\approx 2.5\mu\Omega\text{-in}^2$
(700psi
 $\sim 5\text{ MPa}$)


Req'd Flat Top Time
 $=0.6\text{ sec}$

Note: assuming constant resistivity along joint




CONTACT PRESSURE & RESISTANCE



FEATURES OF NEW DESIGN




NEW TF JOINT DESIGN







VOLTAGE PROBES FOR IN-SITU JOINT RESISTANCE MEASUREMENT

- commercial spring-loaded coaxial probe
- 2 probes per flag, 1 connected to instrumentation, 1 redundant spare
- all 72 joints monitored (maintenance @ 200A, real time at full current)



FEA USED TO ASSESS STRESSES, DISPLACEMENTS, CONTACT PRESSURES





LOAD CASES EXAMINED

- Time Points
 - START OF FLAT TOP (SOFT)
 - END OF FLAT TOP (EOFT)
 - END OF PULSE (EOP)
- Conditions
 - Normal
 - Off Normal
 - ✓ Low Preload (60%)
 - ✓ High Friction Coefficient
 - ✓ Low Friction Coefficient


THERMAL ANALYSIS

Max. Temperature of 94°C Well Below Limit of 120°C



Contact Region

OFF-NORMAL CASE: 60% PRELOAD



- Peak Temperature $\approx 3^{\circ}\text{C}$ Higher
- Temperature Distribution Different
- Current Redistribution Beneficial



MAIN DESIGN IMPROVEMENTS

| <i>Feature</i> | <i>Old Design</i> | <i>New Design</i> |
|-------------------------------|--|--|
| Hub Stiffness | Lacking in Stiffness | Very stiff. Boxes form webs with disks like I-beams |
| Flag Bolts/Inserts | Four 5/16" bolts @ 2500#, marginal friction to carry shear | Four 3/8" studs @ 5000#, doubling of preload |
| | Dual purpose bolts, combined tension and shear functions | Shear Shoes |
| Shimming | Manually selected G10 shim stock | Flags potted in boxes |
| Resistance Measurement | 10A Biddle measurement on disassembled joint, 1 $\mu\Omega$ resolution | 200A in-situ measurement \approx 20x enhanced resolution, plus real time |

All defects contributing to original failure have been addressed

FIBER OPTIC TEMPERATURE, STRAIN, DISPLACEMENT MEASUREMENTS

- Four Flags (inner, outer, top, bottom)
- Hub and Flag twist angle (top, bottom)
- Spline (top only)




FISO Technologies, Inc.

PROTOTYPE TESTING

• Mechanical Tests

- ✓ Full in-plane load, cycled
- ✓ Full lateral load, static
- ✓ 50,000 cycles



• Electrical Tests

- ✓ Full current at full I^2T
- ✓ Full in-plane and lateral load, static
- ✓ 100 pulse current cycles



FABRICATION UNDERWAY AT PPPL



SCHEDULE

| | | |
|---------------------|--|---------|
| | 1. TF Coil Repair Review | Apr '03 |
| | 2. Complete 24 Outer Conductor Machining | Jun '03 |
| | 3. Complete 12 Inner Conductor Machining | Aug '03 |
| | 4. TF Repair FDR | Aug '03 |
| | 5. Complete Insulating TF Conductors | Sep '03 |
| Present Status → | 6. Complete Assembly/Mold of TF Bundle | Oct '03 |
| | 7. Test Inner TF Bundle | Nov '03 |
| | 8. Reinstall TF Bundle into center stack | Nov '03 |
| | 9. Begin Pre-Op ISTPs | Feb '04 |
| | 10. Ready for Plasma Operations | Feb '04 |
| | 11. Project Completion | Feb '04 |

Outage Duration ~ 1 year

CONCLUSIONS

- New Design Corrects All Defects of Original Design
- Follow-on Activities Will Increase Confidence
 - ✓ Mechanical Prototype Testing
 - ✓ Electrical Prototype Testing
 - ✓ Instrumentation During Commissioning and Operations
 - resistance measurement (200A maintenance and real-time) system
 - temperature, strain, displacement