

**CICADA  
ENGINEERING  
SPECIFICATION**

DOCUMENT NO.  
TFTR-10B4-H404A

PAGE 1 OF 14

DATE - 6/24/82

SUBJECT

Timing Module Type 404

PREPARED BY  
*Joe Bosco* for *Paul*  
P. Sichta *Sichta*

APPROVED BY

*Joe Bosco 6/28/82*  
CICADA HARDWARE

*Linda Hanson*  
CICADA DEVICE SUPPORT

*Paul R. Sichta 6/27/82*  
DATA ACQUISITION MANAGER

*[Signature]*  
CICADA MANAGER

**REVISIONS**

DATE	DESCRIPTION
6/24/82	Sections 4.0, 6.11.11, 6.11.12 and 6.12 revised Figures 10.1 and 10.2 revised

## 1.0 Abstract

This specification, in conjunction with reference documents, sets forth all characteristics of the subject module. The intended use of this document is to provide a minimum design goal for the module as well as a working document for subsequent users.

## 2.0 Reference Documents

2.1 IEEE Standard Modular Instrumentation and Digital Interface System (CAMAC), 1975. The Institute of Electrical and Electronic Engineers, Inc.

2.2 Telemetry Standards (Revised January 1971) IRIG, Document No. 106-71.

2.3 USA Standard Codes for Information Exchange, USAS X3.4-1968, ANSI X3.16-1966.

2.4 Printed Circuit Artwork Specification, Document TFTR-10A2-H53A.

2.5 Printed Circuit Board Fabrication and Assembly Specification, Document TFTR-10A2-H54A.

2.6 PEP, Texas Instruments Bulletin, CR-114.

2.7 Electronic Schematic Specification, Document TFTR-10A2-H55.

2.8 Standard Timing Pulse Specification, Document TFTR-10A2-H57.

2.9 Facility Clock Subsystem Specification, Document TFTR-10B4-H401.

2.10 Reliability, Quality Control and Temperature Cycling Specification, TFTR-10A2-H58.

## 3.0 Introduction

The Timing Module when used in conjunction with the CICADA Facility Clock Subsystem provides the means for generating multiple timing signals throughout the Tokamak Fusion Test Reactor (TFTR) site at Princeton. In normal operation Timing Modules will continuously monitor a bi-phase encoded clock signal. Upon recognition of a particular code the Timing Module will start a count of clock pulses and then output a single timing pulse, the selection of assigned code as well as the counting time will be preselected by the CICADA computer system.

#### 4.0 Basic Features

The Timing Module shall be housed in a double (2x) width CAMAC module and shall conform to the requirements defined by the CAMAC standard (reference 2.1). In addition to the standard CAMAC Dataway connections the module shall have one "Facility Clock" input channel and eight (8) independent output channels. The "Facility Clock" input shall be interfaced via a dedicated point on the Dataway Connector and the output channels shall be interfaced via a standard rear mounted auxiliary connector. The module shall function by monitoring the "Facility Clock" signal, which will be encoded in Bi-Phase Level format, (reference 2.2), for recognition of various assigned codes. Upon recognition of an assigned code the module shall cause the appropriate output channel(s) to go into an active state. When active, an individual output channel shall start a count of clock pulses which shall be internally derived from the encoded Facility Clock input. At the conclusion of the count the channel shall output a single timing pulse signal. The counting time for each output channel shall be independently assigned by CAMAC commands and may vary from one microsecond (1us) to approximately sixteen minutes (16 min). Code assignment for individual output channels shall be by CAMAC commands. Each output channel shall be capable of responding to any subset of sixteen (16) dedicated codes. A given channel will respond to all its assigned codes in the same manner. An additional feature of the module shall be the ability to respond to a dedicated "emergency stop" code. Upon recognition of the "emergency stop" code, the module shall reset all internal counters and output a pulse on all "emergency stop" channels. The assignment of "emergency stop" channels shall be accomplished by the placement of internal switches. All channels, however, will reset in response to the "stop" code and will be inhibited from issuing an output pulse unless they are strapped as an "emergency stop" channel. Also, the module will accept simulated event codes via the CAMAC dataway write lines. When properly formatted, the module will accept the data and treat it as if it came from the TFTR Facility Clock system. In the case of "events" coming from both the dataway and the facility clock system, the facility clock system will have the higher priority.

## 5.0 Mechanical Characteristics

5.1 The module shall conform to mechanical specifications as indicated in reference 2.1.

5.2 The module shall be a double (2x) width CAMAC module.

5.3 The electrical components of this module are to be mounted on a high quality flame retardant epoxy glass printed circuit board such as NEMA Type FR-4 or equivalent. See reference specification 2.5.

5.4 This module is to contain all necessary mechanical components for insertion into a standard CAMAC crate. See reference specification 2.1.

5.5 All components are to be identified with a standard manufacturer's part number or standard method of marking (e.g., resistor color coding).

5.6 All electrical components are to be mounted on only one side of the board.

5.7 The condition of this module is to be monitored by LED's located on the module front panel. See Figure 10.1 for the suggested front panel layout. All lettering on the front panel shall be either engraved or silkscreened. The front panel material shall be aluminum with an iridite finish with contrasting colored lettering.

5.8 The 36 pin card edge connector (auxiliary connector) must mate with a Viking 3V18 connector (or equivalent). The card edge connector must be marked with pin 1 on top and pin 18 on the bottom on each side of the card.

5.9 All components are to be assigned an identifying part name (e.g., R1, C2, etc.) which is to be cross-referenced to the manufacturer's part number on the electrical schematic associated with this module. See reference specification 2.7.

5.10 Connector pin assignments shall conform to Figure 10.2.

## 6.0 Electrical Characteristics

6.1 This module must conform to the electrical requirements outlined in reference specification 2.1.

6.2 Whenever possible, low power circuitry (such as the 74LS series) shall be used to minimize power dissipation.

6.3 The module must derive its input power from the standard +/- 24 volt and +/- 6 volt CAMAC supply voltages.

6.4 Input/output signal characteristics for CAMAC Dataway operations shall conform to specifications as indicated in reference 2.1.

6.5 The Facility Clock input signal shall be a TTL compatible signal. The data format shall be as defined by reference 2.9, Section 6.3.2. The base frequency of the encoded Facility Clock signal shall be variable from 0.8MHz to 1.6MHz. The module shall operate over the fully frequency range and slew rate of the Facility Clock as defined by reference 2.9, Section 6.2.1.

6.6 The module shall continuously monitor and decode the Facility Clock signal. All elements of the ten bit code frame shall be tested for proper format as defined by reference 2.9. The module shall not respond unless all ten bits are determined to be correct. The module shall be capable of responding to octal codes 141/8 through 157/8. Upon recognition of an assigned code, the module will cause channel(s) assigned to the code to start counting. Any number of channels may be assigned to any code and any channel may be programmed to respond to any subset of the fifteen allowable codes. A given output channel will respond to all of its assigned codes in the same way.

Code 140/8 shall be designated as the "emergency stop" code. All output channels will respond to this code in one of two ways. Channels shall be designated as "stop" channels or "not stop" channels by the positioning of switches internal to the module. All channels strapped as "stop" channels shall respond to code 140/8 by outputting a timing pulse within 2 microsecond of receipt of the code, as measured from the trailing edge of the Facility Clock stop bit and the leading edge of the output timing pulse. "Stop" channels that are active (counting) when the "emergency stop" code is received shall be reset so that a second timing pulse will not be transmitted for that channel. Channels strapped as "not stop" channels shall take no action in response to the "stop" code if they are in an inactive (non-counting) state. "Not stop" channels, active (counting) when a "stop" code is received shall be reset and the timing pulse that would normally occur at the end of the count shall be inhibited.

Internal programming of the module (codes, count times and clock rates) shall not be affected by the receipt of an "emergency stop" code. All channels shall continue to respond to incoming codes after an "emergency stop" has occurred.

6.7. Individual output channels shall start a new cycle if one of its assigned codes is sensed while the channel is in its active (counting) state.

6.8. The module shall internally derive a clock signal from the Facility Clock for selective use by individual delay counters. The module shall provide three additional clock signals whose frequencies shall be counted down from the fundamental of the Facility Clock frequency, in the ratios of 1/10, 1/100 and 1/1000. Individual channels (8) shall selectively utilize one of the four (4) internal clocks for their respective delay counter. Selection of clock shall be accomplished by CAMAC commands.

6.9. The module shall provide, for each output channel, the capability for counting up to one million (10<sup>6</sup>) clock periods. The accuracy of the delay time shall be +/- 1 clock period, (period of selected clock) and shall be measured from the trailing edge of the Facility Clock stop bit and the leading edge of the output pulse (see Figure 10.3).

6.10. The timing pulse output signal (8 channels) shall be transformer coupled and conform to the requirements defined by reference 2.8 (Standard Timing Pulse).

#### 6.11 CAMAC Command Description

##### 6.11.1 Command #1 Initialize or Clear [Z+C]

These commands must set all channels to an inactive state and disable all outputs.

##### 6.11.2 Command #2 Read Module Number [F(6).A(0)]

This command gates the module identification number (decimal 404, binary 000110010100) on the Dataway read lines R1 through R12 with the LSB on R1.

##### 6.11.3 Command #3 Read Assigned Code [F(1).A(\*)]

This command gates a binary representation of codes assigned to channel (\*) onto Dataway read lines R1 through R16. Codes 141/8 through 157/8 shall correspond to lines R2 through R16 respectively. Dataway read line R1 shall be used to gate the channel's strapped designation. A logic '1' on line R1 will indicate that the channel is strapped as an "emergency stop" channel.

#### 6.11.4 Command #4 Read Count and Clock [F(2).A(\*)]

This command gates the assigned delay count length, for channel (\*) onto Dataway read lines R1 through R20 with the LSB on R1, and the selected clock for channel (\*) onto Dataway read lines. R1 and R22 in binary format as shown below.

Clock	R22	R21
1MHz	0	0
100KHz	0	1
10KHz	1	0
1KHz	1	1

#### 6.11.5 Command #5 Write Code [F(16).A(\*)]

This command loads the information on Dataway write lines W1-W16 to set assigned codes for channel (\*). Codes 141/8 through 157/8 shall correspond to lines W2 through W16 respectively.

#### 6.11.6 Command #6 Write Delay [F(17).A(\*)]

This command loads the information on Dataway write lines W1 through W22 to set the assigned count and clock for channel (\*). The information on lines W1 through W20 shall determine the count length in binary format with the LSB on W1. The information on lines W21 and W22 shall determine the assigned clock. The clock selection shall follow the format delineated in paragraph 6.11.4.

#### 6.11.7 Command #7 Clear Code [F(9).A(\*)]

This command clears all code assignments for channel (\*) and disables channel (\*) output.

6.11.8 Command Accepted (X) must be returned as logical "1" for all commands received and recognized as one that it is equipped to perform.

6.11.9 Q must be returned as a logic "1" for all addressed commands received by the module.

6.11.10 The module shall not generate or respond to CAMAC signals L, I, or B.

6.11.11 Command #8 Emergency Stop [F(26).A(0)]

This command will cause the module to respond as if an "emergency stop" code were received via the Facility Clock System. That is, all active counters will be reset and a pulse will be immediately issued on any channel switched to the "emergency stop" mode (see Section 4.0).

6.11.12 Command #9 Activate Event Code [F(18).A(1)]

This command loads the information on dataway write lines W1-W17 to force an event code into the module. The module would then treat this code as if it were received via the TFTR Facility Clock System. The information on the dataway must be formatted as shown below:

OCTAL CODE	HEX DATA FORMAT (W1-W24)
140	00 00 5F
141	00 00 1E
142	00 00 1D
143	00 00 5C
144	00 00 1B
145	00 00 5A
146	00 00 59
147	00 00 18
150	00 00 17
151	00 00 56
152	00 00 55
153	00 00 14
154	00 00 53
155	00 00 12
156	00 00 11
157	00 00 50

6.12 The module shall provide two LED indicators mounted on the front panel. One will be labelled "N" and will illuminate for 200ms whenever the module is addressed. The second LED will be labelled "code active". This will illuminate for 200ms whenever the module receives a valid event code; whether generated via the facility clock or the dataway write lines. The LED does not indicate whether any channels were programmed to respond to the event code.

## 7.0 Environmental Data

7.1 The module must operate over an ambient temperature range of 0 to +50°C.

7.2 The module must operate over a relative humidity range of 10% to 90%. It is not a requirement that the module operate under conditions of water condensation.

7.3 The module must not be affected by an external magnetic field changing at a maximum rate of 100 gauss per second with a peak magnitude of 50 gauss in any direction.

7.4 The module must operate in a radiation environment of 1 rad/second (peak) with a total integrated lifetime dose of 1000 rad.

## 8.0 Reliability

8.1 The module must have an expected life of at least ten years under normal operating conditions. The module shall be rated for continuous operation.

8.2 All components on this module must be of high quality and have a MTBF rating of at least 10<sup>6</sup> hours. All components must have an exact replacement available from a second source manufacturer or have a readily available equivalent.

8.3 All integrated circuits used in this module must have undergone a burn-in procedure as provided by Texas Instruments PEP-3 Processing (see reference document 2.5). Equivalent processes from other manufacturers is acceptable.

## 9.0 Safety

9.1 All components of this module must be of flame retardant material.

	B	A	
Clean Earth (CE)	1	1	CE
CH1, HI	2	2	CH1, Low
CE	3	3	CE
CH2, HI	4	4	CH2, Low
CE	5	5	CE
CH3, HI	6	6	CH3, Low
CE	7	7	CE
CH4, HI	8	8	CH4, Low
CE	9	9	CE
CH5, HI	10	10	CH5, Low
CE	11	11	CE
CH6, HI	12	12	CH6, Low
CE	13	13	CE
CH7, HI	14	14	CH7, Low
CE	15	15	CE
CH8, HI	16	16	CH8, Low
CE	17	17	CE
	18	18	

FIGURE 10.2

PIN ASSIGNMENT, AUXILIARY CONNECTOR

(Viewed from front of crate)





Figure 10.3 "On Time" Mark



PRINCETON PLASMA PHYSICS LABORATORY  
**ENGINEERING NOTE**

PROJECT

SERIAL-CATEGORY

PAGE

SUBJECT

NAME

DOUBLE WIDTH MODULE - TIMING MODULE H404

DATE

6/14/82

REVISION DATE

TIMING MODULE  
H404



N



CODE  
ACTIVE



INTER-OFFICE CORRESPONDENCE

TO : Distribution

DATE : 04 November 1986

FROM : Paul Sichta *PS*

SUBJECT : H404A Timing  
Modules

Recently, another problem with the CAMAC H404A Timing Module has been discovered. The problem will be referred to as the 'CH8' problem. The effect of the problem is an extended timing delay for channel eight of the timing module. This problem occurs only when all of the following events transpire :

- 1) Channel 8 has responded to a TFTR Facility Clock event code, and is counting down.
- 2) While CH8 is counting down, another of the timing module's channels (CH1-CH7) responds to a TFTR clock event code and loads its delay counter.

When (1) and (2) happen, CH8's delay counters are inadvertently reloaded. The reloading of CH8's delay counters is due to an extraneous pulse in the H404A circuitry. The pulse is due to a race condition in the logic design.


A solution to this problem is to alter the timing of the appropriate circuitry on the H404A module. The alteration will extend the duration of a pulse generated by IC12-5 on Board A. The pulse is extended from 50 ns to 100 ns by changing R6 from 5.1 Kohms to 22 Kohms. This change will slow down the scan-and-load process for the timing module. At worst case, when all eight channels recognize the same event code, CH1 and CH8 can be skewed by an additional 1 microsecond. I estimate that the module upgrade will expend two technician hours. (retrieve, upgrade, test, install).

I recommend that all timing modules in the field be upgraded to incorporate the R6 change. I would like to see the following transpire :

- 1) Bruce Holendonner will provide an inventory of all H404A timing modules. This will be used to plan and record all upgrades.
- 2) Each engineer will provide me with a list of their CAMAC systems which use channel eight of the timing module. These modules will be upgraded first.
- 3) The remaining modules will be changed on non-run weeks according to a TBD schedule, coordinated by myself.
- 4) H404A modules not upgraded before TFTR startup will be labeled warning the user not to use channel eight.

The computer division should provide the user community with an 'as advertised' CAMAC system. This includes analog calibration and timing system accuracy. In order to provide this to our user's, as well as effectively troubleshoot and maintain systems using our divisional staff, all timing modules should be upgraded.

Distribution : Hardware Engineers  
N. Sauthoff, G. Oliaro, W. Rauch, S. Davis



H404A TIMING MODULE BOARD 'A'  
11-4-86 P.S

## R10 AJUSTMENT ON 404A

IT WAS FOUND THAT THE PULSE WIDTH ON U25 PIN 13 ON THE "B" BOARD WAS NOT AJUSTED AT ITS OPTIMUM WHEN SET AT 710 nSEC. IF THE AJUSTMENT WERE TO DRIFT TO 780nSEC, THE 404A WOULD WORK ON THE BENCH, BUT IF THE DUTY CYCLE OF THE P1 CLOCK WAS WORSE THAN 50/50, THEN THE MODULE WOULD NO LONGER RECOGNIZE A P1 CODE. THIS HAPPENED ON MANY 404A'S. I FOUND THAT THE OPTIMUM AJUSTMENT IS 625nSEC. ALL OF THE 404A'S I HAVE REPAIRED OR TESTED SINCE JULY 1987 HAVE BEEN AJUSTED TO 625nSEC.

**INTER-OFFICE CORRESPONDENCE**

=====  
**To : Distribution** **Date : 26 September 1988**  
**From : P. S**ichta/G. Kolinchak/<sup>OK</sup>  
**J. Wertenbaker** J.S.W. **Subject : 404 Module Problems**  
=====

Recently, two more problems were found associated with the 404 Timing module. The first involves missed codes and the second the inadvertent clearing of code registers. Previous problems are described in two memos from P. Sichta dated February 10, 1986 and November 4, 1986.

Occasionally, the NB 404's would miss Facility Clock System event codes. The missed code problem was difficult to identify because so many variables are involved; such as if the 404 is located in the lower numbered slots, what type of modules are in the crate, and the level/type of noise found in the crate. The primary signal which sets up the condition that causes the 404 to miss a code is the dataway's Busy signal, generated by the L-2 crate controller. Most crates have an open, or unloaded Busy line. An unloaded/unclamped dataway signal tends to ring. When Busy goes low (active), it swings from +5.2 v to -4.0 v, then up to +2.2 v, then dampened  $e^{-bt}$  at 33 MHz. Since the Busy line is adjacent to the P1 (Facility Clock) line, the P1 line picks up about a 2v positive spike. If this spike occurs during a critical time window, the 404's internal edge counter incorrectly perceives a start-of-code. This sets up a condition which causes the 404 to miss the next authentic code.

We feel that this is not a 404 design problem, but nevertheless recommend the following 404 upgrade :

a) Add a schottky diode (Motorola MBD501) clamp to ground from the Busy line (B-board) on the 404. This should clamp the negative swing to -0.6v, and reduce the coupling to P1.

b) Replace the P1 edge counter (IC33, B-board) in the 404 with a 74LS132 schmitt trigger device to raise the input threshold.

The second problem is the clearing of the code registers. This problem is also associated with a noisy backplane. It first appeared in a Test Cell Basement rack on NB shots >20 MW. The CAMAC dataway Z and C lines are NANDed to form a CLEAR-CODES strobe in the 404 module. If a spurious glitch travels along the C or Z lines, all code registers in the module will be cleared, similar to powering up the module (according to the IEEE's CAMAC spec, the C or Z lines should be gated with dataway strobe S2, to prevent such spurious effects). Placing a .01 uf capacitor on the output of the NAND gate (IC29-3,B-board) has been demonstrated to mask the spurious C/Z glitches.

We recommend that these three modifications be implemented on 404 modules to increase their reliability. A *GREEN* dot on the front panel of the 404 module will indicate that changes described herein, as well as all previous changes, have been implemented.

**Each cognizant engineer will be responsible for having the modifications implemented on their systems.**

cc: Hardware Engineers  
G. Oliaro  
W. Rauch  
N. Sauthoff

PRINCETON UNIVERSITY: PPPL COMPUTER DIVISION

TO: Distribution

DATE: 8/19/88

FROM: G. Kolinchak  
J. Wertenbaker

SUBJECT: 404 module missing  
codes

---

This problem is hard to indentify because so many variables are involved. We have to treat the problem as the probability for a 404 Timing Module to miss a code. If the 404 Module is located in lower numbered slots, the type of modules in the crate and level/type of noise found in the crate are just some of the varaibles. The signal that sets up the condition that causes the 404 to miss the code is the Busy signal, generated by the L2 Crate Controller. This signal is only used by a few modules like a Block Transfer Unit or Auxiliary Crate Controller. Most of our crates have an open Busy control line, driven by the L2. The Busy line just happens to be tuned to 33MHz. When the Busy goes low, it swings from +5.2v to -4.0v then back to +2.2v then dampened  $e^{-bt}$  at 33MHz. This Busy line happens to be next to the P1 Facility Clock line, which picks up a  $>2v$  positive spike. The 404 has an edge counter connected to P1. If this spide gets counted within a certain time window, data will be clocked in as a start of a code. This sets up a condition which causes the 404 does not reconize the next real code.

We feel that this is not a 404 design problem, but would recomend the following update to the 404 Module to solve this problem.

- Add a Schottky diode clamp to ground from the Busy line on the 404 Module. This will clamp the negative swing at -0.6v.
- Replace the edge counter in the 404 input, with an SN74LS132 schmitt trigger device to raise the input threshold.

We feel that this change will push the probability of missing a code to zero. This could be implemented during the 404 update/calibration that is in progress at this time. This would only add a few minutes to the 4 hour procedure.

Distribution:

W. Rauch, G. Olairo, N. Sauthoff

cc: Hardware engineers.

## 404A Timing Module Test, Green-Dot Modification, and Repair Checklist

R6=22K on left board (A), was previously 5.1K, ¼ watt

Remove C27 on right board (B); there is an error on the artwork. C27 isn't a bypass capacitor and it will cause problems if it is present.

U33 should be 74LS132, not 74LS00 on B board, replace if it's not a 74LS132

U29 0.01uf capacitor pin 3 to ground on B board (solder side, see picture 1)

C36 (B board) should be 100pf, some BiRa boards have 10pf instead

Check C37 (B board) polarity, it may be reversed

Schottky diode (Motrola MBD501) from dataway pin 1R (BUSY) to ground on B board. (Anode goes to ground) (See Picture 2)

Test switches for damage due to solvent, replace if necessary. (Legacy problem, computer program will test)

Pot=625nSec pulse width on U25 pin 13 (B board) and put label on front "625nSec (date)"

Test diode voltage drop, shouldn't be greater than 0.9V on both boards. Replace any glass diode with 1N4006 or better power rating.

Test delay accuracy. If it fails, insure U15 (B board) 74LS00 is in a socket and make it Signetics. This is an oscillator circuit, and other brands will oscillate at the wrong frequency. Also, R6 on the A board should be 22K, as mentioned above. This affects the delay accuracy test. If the delay accuracy test still fails, see the "Proper Timing Of 404A R6 Board A (Left)" section, after Picture 2.

Clean boards

Clean fingers


Thoroughly test board

Put label on side with OK, tester's initials, and date


Put a green dot on the top of the front panel

Log its S/N in sheet

Picture 1



Picture 2




## PROPER TIMING OF 404A R6 BOARD A (LEFT)

Top trace=U60 pin 6 (Enable for 74LS193 load input, going through 74LS138)

Bot trace=U64 pin 5 (74LS193 Clock input)

.2uSec/Div, 1V/Div

The bottom trace is not allowed to go through any transition unless the top trace is low. The rising edge of the bottom trace may line up with the rising edge of the top trace, but must not happen immediately before it. Top trace=4Mhz, 8 pulses. This timing can be adjusted by changing the value of R6 on the "A" board. It is always best to start with 22K, then adjust as necessary. It is OK to use 1% precision resistors to fine tune this timing if 5% resistors don't achieve the proper timing. 1% resistors come in more standard values than 5% resistors, so it is more likely to find just the right value that works.



# Facility Clock Codes

Octal code	404 Bit #	404 F(16) Hex Value	Clock Encoder F(16)	404 F(18)	Code Name
140	1	1	60	5F	Emerg Stop (Not used)
141	2	2	E1	1E	SOC
142	3	4	E2	1D	SOS
143	4	8	63	5C	T(-60)
144	5	10	E4	1B	SOP
145	6	20	65	5A	SOI (T(-1))
146	7	40	66	59	SOD (T(0))
147	8	80	E7	18	NBI
150	9	100	E8	17	T(+D)
151	10	200	69	56	EOD
152	11	400	6A	55	EOP
153	12	800	EB	14	Link Self Test
154	13	1000	6C	53	PC Fault
155	14	2000	ED	12	PC Event
156	15	4000	EE	11	FBL
157	16	8000	6F	50	Not used