High-k update

- Walked beam around in-vessel
 - No signal
- Verified microwave power entering vessel
- Poor tracking
 - Added amp to reference channel – tracking good now
- Power supplies ok
- Digitized noise does not vary
 - Suggests electronics problem
- Trigger ok
- Mixers are alive
- Initial test of I/Q electronics ok

- 2nd stage amps ok
- Installed crystal detector after 2nd stage amp
 - Signal observed
 - Suggests mixer, preamp (20 dB), and 2nd stage amp (40 dB) are all ok
- Plans
 - Remove attenuators (20 dB) before I/Q electronics
 - Isolated test of preamps
 - Revisit I/Q electronics