THE PLANT OF THE FUTURE

Staffing:
It takes about 14 people minimum to run DIII-D (not counting managers)
What about a plant?

Where can you realistically put it?

It will be a huge facility

It will be radioactive

It will need a lot of cooling

It will need to be very simple, say a neutron detector and some anti-disruption hardware

It will need to be fully FULLY automated