




► Feedback density control by FReTIP

- FC1 & FC2 connected to PCS digitizer
- 3 tasks in PCS programming (+..)
- a graduate student from UC Davis

Both density-converted signals from the fringe counter and the I-Q mixer are in good agreement with their own features.



after 5 kHz PCS digitizer



(1) checking system ready

(2) hitting bottom and ceiling issue

(3) fringe jump removal

XMP

