

	TF and PF waveforms from shot 125201			
	PF5 and PF4 flat top from 0.10 - 0.70s			
	TF flat top from 0 - 0.70 s			
	Adjust gas pressure to 5x10e-5 torr . See shot 125201			
	Stretch beams to 400 ms pulse length . NBI timing 0.25 - 0.65 s			
# of				
Shots	TF	PF5	PF4	Shot Numbers / Comments
1 <input type="checkbox"/>	4.5 kG	2 kA	0	
1 <input type="checkbox"/>	4.5 kG	4 kA	0	
1 <input type="checkbox"/>	4.5 kG	7 kA	0	
1 <input type="checkbox"/>	4.5 kG	10 kA	0	
1 <input type="checkbox"/>	4.5 kG	13 kA	0	
1 <input type="checkbox"/>	4.5 kG	16 kA	0	
1 <input type="checkbox"/>	4.5 kG	19 kA	0	
1 <input type="checkbox"/>	4.5 kG	0	2 kA	
1 <input type="checkbox"/>	4.5 kG	0	5 kA	
1 <input type="checkbox"/>	4.5 kG	0	9 kA	
10 at 4.5 kG				
1 <input type="checkbox"/>	5.5 kG	0	9 kA	
1 <input type="checkbox"/>	5.5 kG	0	5 kA	
1 <input type="checkbox"/>	5.5 kG	0	2 kA	
1 <input type="checkbox"/>	5.5 kG	2 kA	0	
1 <input type="checkbox"/>	5.5 kG	4 kA	0	
1 <input type="checkbox"/>	5.5 kG	7 kA	0	
1 <input type="checkbox"/>	5.5 kG	10 kA	0	
1 <input type="checkbox"/>	5.5 kG	13 kA	0	
1 <input type="checkbox"/>	5.5 kG	16 kA	0	
1 <input type="checkbox"/>	5.5 kG	19 kA	0	
10 at 5.5 kG				
1 <input type="checkbox"/>	3.5 kG	19 kA	0	
1 <input type="checkbox"/>	3.5 kG	16 kA	0	
1 <input type="checkbox"/>	3.5 kG	13 kA	0	
1 <input type="checkbox"/>	3.5 kG	10 kA	0	
1 <input type="checkbox"/>	3.5 kG	7 kA	0	
1 <input type="checkbox"/>	3.5 kG	4 kA	0	
1 <input type="checkbox"/>	3.5 kG	2 kA	0	
1 <input type="checkbox"/>	3.5 kG	0	9 kA	
1 <input type="checkbox"/>	3.5 kG	0	5 kA	
1 <input type="checkbox"/>	3.5 kG	0	2 kA	
10 at 3.5 kG				